


CORNER RECORD

APN No. 098 - 0346 - 019 - 00 (Optional)

Document Number

CR 1496City of LIVERMORECounty of ALAMEDA

, California

Brief Legal Description PARCEL B, PM 4006, 143 PM 11, ALAMEDA COUNTY

CORNER TYPE

Government Corner ☐Control ☐Meander ☐Property ☒Rancho ☐Other ☐

Date of Survey _____

COORDINATES

(Optional)

N. _____

E. _____

Zone _____ Datum _____

Elev. _____

Corner - Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

In compliance with Section 8771 of the Professional Land Surveyors' Act, this corner record is being filed to ESTABLISH ____ / REESTABLISH ____ the position of an existing monument PRIOR ____ / SUBSEQUENT ____ to street or highway reconstruction. (Use this portion only when applicable.)

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: USED EXISTING STREET MONUMENTS TO REESTABLISH THE PROPERTY CORNERS FOR PARCEL B, PM 4006, 143 PM 11.

A description of the physical condition of the monument as found and as set or reset: ONE CORNER REMOVED FOR WALL CONSTRUCTION, FOOTING PREVENTS RESET OF CORNER, ONE I.P. STILL EXISTS IN GOOD CONDITION, NOTHING WAS ORIGINALLY SET FOR REMAINING CORNERS, SET 5/8" REBAR WITH ALUMINUM CAP STAMPED "LAMB SURVEYING, INC., LS 5678".

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on APRIL 25 2001.

Signed Jon M. Lamb L.S. or R.C.E. Number L.S. 5678




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 4.30.2001 and examined and filed 4.6.2001.

Signed Russell R. Penland Title Deputy County Surveyor

Expiration
Date: _____



County Surveyor's Comment _____

